

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6A plotting all of the measurement points in the mapping measurement





Fig. 6B example of expressing as contour an orientation distribution function to specific index.








Fig. 9A





Fig. 9B



Fig. 9C










Fig. 10








Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17A




Fig. 17B




Fig. 18




Fig. 19




Fig. 20 A




Fig. 20 B




Fig. 21




Fig. 22A




Fig. 22B




Fig. 22C




Fig. 22D




Fig. 22E

Fig. 23A




Fig. 23B





Fig. 23C






Fig. 24A




Fig. 24B




Fig. 24C




Fig. 24D

Fig. 25A




Fig. 25B




Fig. 25C




Fig. 25D




Fig. 26 A




Fig. 26 B